


















1




T-30 LLAVE TORX
T-30 TORX WRENCH



2




A = 27




A = 40






3




T-30 TORX-SCHLUESSEL
T-30 TORX WRENCH




4




1




2








3




4




5









1




2




3




4





X = max. 900 mm





1





2




3




4





X = max. 900 mm




1





2





3




4









5




6




X = max. 900 mm








1




2




3






4





$X = \text{max. } 900 \text{ mm}$





1




2








3















4



X = max. 900 mm





X = max. 900 mm

